UNCLASSIFIED

AD NUMBER

AD367468

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited


FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

THIS PAGE IS UNCLASSIFIED



COMFRESIM

BUREAU OF SHIPS GROUP

TECHNICAL INSPECTION REPORT


OPERATION CROSSROADS. U.S.S. SKIPJACK (SS184).
TEST BAKER, VOLUME 2[U].

Bureau of Ships Group technical inspection rept.,

1947 12 200p.

U. S. GOVERNMENT AGENCIES MAY OBTAIN COPIES OF THIS REPORT DIRECTLY FROM DDC. OTHER QUALIFIED DDC USERS SHALL REQUEST THROUGH

Director
Defense Atomic Support Agency
Washington, D. C. 20301



\4300

CONFIDENTIAL




AB-CR-SM-6500-5. Crushed deck at frames 29-31 port.

SEÇRET

USS SKIPJACK (SS184)

Page 2 of 200 Pages



AB-CR-SM-6500-7. Buckled supports for superstructure at frames 29, 30 and 31, port.

USS SKIPJACK (SS184)

Page 3 of 200 Pages



AB-CR-SM-6500-9. Compression failure of superstructure bracket at frame 34, port looking outboard.

Page 4 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-SM-6500-11. Superstructure bulkhead at frame 59, port, looking forward.

ひたしれた」

USS SKIPJACK (SS184)


Page 5 of 200 Pages



AB-CR-SM-6501-2. Crushed main deck, frames 173-179, looking aft.

Page 6 of 200 Pages


USS SKIPJACK (SS184)



AB-MIG-6518-11. Torpedo tube No. 1 Breech door.

Page 7 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6519-1. Torpedo tube No. 2 Breech door.


Page 8 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6518-12. Torpedo tube No. 3 breech door.

Page 9 of 200 Pages



AB-CR-MIG-6519-2. Torpedo tube No. 4 Breech door.


Page 10 of 200 Pages



AB-CR-MIG-6516-2. Torpedo tube No. 5 breech door.

Page 11 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6516-1. Torpedo tube No. 6 breech door.


Page 12 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6516-3. Torpedo tube No. 7 breech door.

Page 13 of 200 Pages



AB-CR-MIG-6515-11. Torpedo tube No. 8 Breech door.

USS SKIPJACK (SS184)


Page 14 of 200 Pages



AB-CR-MIG-6516-4. Bulge in bottom of torpedo tube number 8.

Page 15 of 200 Pages

USS SKIPJACK(SS184)



AB-CR-MIG-6516-5. Bulge in bottom of torpedo tube number 7.

Page 16 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6524-1. Failure of straps on impulse flasks for after torpedo tubes.

CECRET

Page 17 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6517-9. Dimple in circular hull plating between frames 139 and 141 at the 12' water line.

USS SKIPJACK (SS184)

Page 18 of 200 Pages



AB-CR-MIG-6517-10. Dimple in circular hull plating between frames 139 and 141 at the 7' water line.

Page 19 of 200 Pages



AB-CR-MIG-6517-11. Dimple in circular hull plating between frames 141 and 143 at the 7' water line.

USS SKIPJACK (SS184)


Page 20 of 200 Pages




AB-CR-MIK-6529-4. General view of dimples in single hull plating - port side of forward torpedo room and trim tank.

Page 21 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIK-6530-1. General view of dimples in single hull plating - port side of after engine room, from below.



AB-CR-MIK-6529-5. General view of dimples in single hull plating - port side of after engine room, from above.

USS SKIPJACK (SS184)

Page 23 of 200 Pages



AB-CR-MIK-6529-6. General view of dimples in single hull - port side of after torpedo room - from above.



AB-CR-MIK-6529-12. General view of dimples in single hull - port side of after torpedo room, from below.



AB-CR-MIK-6530-2. General view of dimples in single hull - starboard side of after torpedo room, from below.

USS SKIPJACK (SS184)

Page 26 of 200 Pages



AB-CR-MIK-6529-7. General view of dimples in single hull - starboard side of after torpedo room, from above.

Page 27 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIK-6529-10. General view of dimples in single hull - starboard side of forward torpedo room.

USS SKIPJACK (SS184)

Page 28 of 200 Pages



AB-CR-MIK-6529-9. General view of dimples in single hull-starboard side of forward to pedo room.



AB-CR-MIK-6529-8. General view of dimples in single hull - starboard side of forward torpedo room and trim tank.

USS SKIPJACK (SS184)

Page 30 of 200 Pages




AB-CR-MIG-6523-7. Dimples in non-circular pressure hull - frames 13-17 port.

Page 31 of 200 Pages

USS SKIPJACK (SS184)




AB-CR-MIG-6523-8. Dimples in non-circular pressure hull - frames 17-21 port.




AB-CR-MIG-6523-9. Dimples in non-circular pressure hull - frames 21-25 port.

USS SKIPJACK (SS184)




AB-CR-MIG-6523-11. Dimples in non-circular pressure hull - frames 24-27 port.



AB-CR-MIG-6523-12. Dimples in non-circular pressure hull - frames 28-33 port.

USS SKIPJACK (SS184)


Page 35 of 200 Pages



AB-CR-MIG-6526-4. Dimples in non-circular pressure hull-frames 32-35 port.

Page 36 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6527-10. Dimples in non-circular pressure hull - frames 155-162, port, from keel to maximum beam.

USS SKIPJACK (SS184)


Page 37 of 200 Pages



AB-CR-MIG-6527-11. Dimples in non-circular pressure hull - frames 155-159, port from maximum beam to top.

USS SKIPJACK (SS184)


Page 38 of 200 Pages



AB-CR-MIG-6527-12. Dimples in non-circular pressure hull - frames 157-161, port.

USS SKIPJACK (SS184)


Page 39 of 200 Pages



AB-CR-MIG-6527-3. Dimples in non-circular pressure hull - frames 160-164, port.

USS SKIPJACK (SS184)


Page 40 of 200 Pages




AB-CR-MIG-6526-12. Dimples in non-circular pressure hull - frames 160-166, port.

Page 41 of 200 Pages

USS SKIPJACK (SS184)




AB-CR-MIG-6526-11. Dimples in non-circular pressure hull - frames 166-170, port.



AB-CR-MIG-6526-10. Dimples in non-circular pressure hull - frames 170-177, port.


Page 43 of 200 Pages



AB-CR-MIG-6526-8. Dimples in non-circular pressure hull - frames 174-177, port.

USS SKIPJACK (SS184)


Page 44 of 200 Pages



AB-CR-MIG-6527-4. Dimples in non-circular pressure hull - frames 172-178, port, maximum beam to top.

USS SKIPJACK (SS184)


Page 45 of 200 Pages



AB-CR-MIG-6526-9. Diraples in non-circular pressure hull - frames 176-180, port, just above keel.

USS SKIPJACK (SS184)


Page 46 of 200 Pages



AB-CR-MIG-6527-5. Dimples in non-circular pressure hull - frames 176-180, port just above keel.

Page 47 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6527-6. Dimples in non-circular pressure hull - frames 176-180, port maximum beam to top.

USS SKIPJACK (SS184)

Page 48 of 200 Pages



AB-CR-MIG-6527-7. Dimples in non-circular pressure hull - frames 179-184, port.

Page 49 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6527-9. Dimples in non-circular pressure hull - frames 181-183, port.

USS SKIPJACK (SS184)

Page 50 of 200 Pages



AB-CR-MIG-6527-8. Dimples in non-circular pressure hull - frames 181-185, port.


Page 51 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6525-11. Dimples in non-circular pressure huli - frames 178-184, starboard.


Page 52 of 200 Pages




AB-CR-MIG-6526-1. Dimples in non-circular pressure hull - frames 179-184, starboard.

USS SKIPJACK(SS184)

Page 53 of 200 Pages



AB-CR-MIG-6525-6. Dimples in non-circular pressure hull - frames 176-181, starboard, lower part.



AB-CR-MIG-6525-5. Dimples in non-circular pressure hull - frames 172-178, starboard, lower part.

USS SKIPJACK(SS184)

Page 55 of 200 Pages




AB-CR-MIG-6526-3. Dimples in non-circular pressure hull - frames 174-178, starboard, at 18' water line.


USS SKIPJACK (SS184)

Page 56 of 200 Pages

67:7



AB-CR-MIG-6526-2. Dimple in non-circular pressure hull-frames 171-175, starboard at 18' water line.




AB-CR-MIG-6525-7. Dimples in non-circular pressure hull - frames 157-164, starboard.

USS SKIPJACK(SS184)

Page 58 of 200 Pages

579T



AB-CR-MIG-6525-8. Dimples in non-circular pressure hull - frames 157-162, star pard.

USS SKIPJACK(SS184)

Page 59 of 200 Pages



AB-CR-MIG-6525-9. Dimples in non-circular pressure hull - frames 153-159, starboard.


USS SKIPJACK (SS184)

Page 60 of 200 Pages




AB-CR-MIG-6525-10. Dimples in non-circular pressure hull-frames 27-33, starboard.

Page 61 of 200 Pages




AB-CR-MIG-6525-2. Dimples in non-circular pressure hull - frames 25-29, starboard.



AB-CR-MIG-6528-11. Dimples in non-circular pressure hull - frames 19-24, starboard.


Page 63 of 200 Pages



AB-CR-MIG-6525-1. Dimples in non-circular pressure hull - frames 17-22, starboard-

Page 64 of 200 Pages


USS SKIPJACK(SS184)



AB-CR-MIG-6525-12. Dimples in non-circular pressure hull - frames 13-17 starboard.

USS SKIPJACK(SS184)

Page 65 of 200 Pages



AB-CR-SM-6500-10. Divers repair weld in shell fracture at frame 30, port.

Page 66 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6516-6. View of plating fracture at frame 30, port, looking up from interior.

Page 67 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6529-2. Plating fracture at frame 30, port, after repair weld was removed.


USS SKIPJACK(SS184)

Page 68 of 200 Pages



AB-CR-MIG-6529-3. Plating fracture at frame 30, port, looking up, repair weld removed.


Page 69 of 200 Pages



AB-CR-MIG-6518-5. Dimple in top of non-circular pressure hull - frames 29-31 port.

Page 70 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6518-6. Dimple in top of non-circular pressure hull - frames 30-32 port.

Page 71 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6520-11. Overall view of method for measuring frame distortion of non-circular hull.

USS SKIPJACK (SS184)

Page 72 of 200 Pages



AB-CR-MIG-6520-12. Close up of scribing operation where frame distortion is not abrupt.

Page 73 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6528-1. Distortion of frame 21, starboard, looking forward Note web wrinkle and shell bulge.

Page 74 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6528-4. Bulge in frame 31, port, 4'above tank top - Looking forward.

USS SKIPJACK(SS184)


Page 75 of 200 Pages



AB-CR-MIG-652 -2. Distortion at foot of frame 31, port, looking aft.

Page 76 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6528-3. Flange distortion of frame 32, port, looking outboard.

Page 77 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6516-10. Frame 158, port, showing general collapse and buckled flange.

USS SKIPJACK**(**SS184)

Page 78 of 200 Pages



AB-CR-MIG-6528-6. Collapse of floors at frames 177 and 178, just to starboard of keel. Looking aft.

Page 79 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6528-7. Collapse of floors at frames 177 and 178, just to port of keel. Looking aft.

USS SKIPJACK (SS184)


Page 80 of 200 Pages



AB-CR-MIG-6520-8. Frame 24, starboard. Cracked weld at intersection of face plate in bulkhead with tank top.

Page 81 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6520-9. Frame 25, starboard, cracked weld at intersection of face plate in floor with tank top.

USS SKIPJACK (SS184)


Page 82 of 200 Pages



AB-CR-MIG-6507-11. Conning tower after bulkhead. Note loose cork.

Page 83 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6507-12. Conning tower forward bulkhead. Note loose cork.

Page 84 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6506-8. Access door to forward escape trunk, dished in at center.

USS SKIPJACK (SS184)


Page 85 of 200 Pages



AB-CR-MIG-6513-11. Starboard dog of after torpedo room loading hatch.

Page 86 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6509-9. Equipment in way of frames 20-21 starboard showing controller for bow plane rigging and capstan motor.

USS SKIPJACK (SS184)

Page 87 of 200 Pages



AB-CR-MIG-6507-2. Forward torpedo tube impulse manifold, after foundation bracket.

USS SKIPJACK (SS184)

Page 88 of 200 Pages



AB-CR-MIG-6507-3. Forward torpedo impulse manifold, forward bracket and bow plane rigging and capstan motor controller.


Page 89 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-12. Edge type strainer, showing failure of foundation brackets and bent wiping shaft.

USS SKIPJACK (SS184)



AB-CR-MIG-6519-7. Accumulator Air Flask in pump room.

Page 91 of 200 Pages


USS SKTPJACK (SS184)



AB-CR-MIG-6520-5. Ship's Air Flask in No. 2B main ballast tank, showing strap failure.

Page 92 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6515-10. Fracture of after, inboard foot of No. 1 turbo blower.

USS SKIPJACK (SS184)

Dage 93 of 200 Pages



AB-CR-MIG-6515-9. Fracture of after inboard foot of No. 2 turbo blower.

USS SKIPJACK (SS184)


Page 94 of 200 Pages



AB-CR-MIG-6511-9. Fracture of housing for low plane hand tilting gear box.

Page 95 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6511-8. Fracture of housing for stern place hand lifting gear box.

USS SKIPJACK (SS184)

Page 96 of 200 Pages



AB-CR-MIG-6: 6-8. Ship's service air compressors and motor terminal box. Note collapsed sound isolation mount.

USS SKIPJACK (SS184)



AB-CR-MIG-6516-7. Radio motor generator sound isolation mount.



AB-CR-MIG-6507-10. Main ballast tank 2 H - flood valve operating gear. Note wooden plug where grease fitting was broken out.

USS SKIPJACK (SS184)


Page 99 of 200 Pages



AB-CR-MIG-6512-7. No. 2 main motor sea suction valve - 100 showing leak under flange.

USS SKIPJACK (SS184)


Page 100 of 200 ges



AB-CR-MIG-6528-10. Outer hull in way of port auxiliary tank - bilge keel down to main keel.

Page 101 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6528-9. Outer hull in way of port auxiliary tank - bilge keel up to the tank top.

USS SKIPJACK (SS184)

Page 102 of 200 Pages



AB-CR-MIG-6526-6. Port side of negative tank.

Page 103 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6520-6. Frame 72, port, at bottom of negative tank. Note shear wrinkles at the two ends.


USS SKIPJACK (SS184)



AB-CR-MIG-6513-3. Buckle in forward bulkhead of port safety tank. Looking outboard.

Page 105 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6513-4. Buckle in floor at frame 90 and after bulkhead of starboard safety tank. Looking outboard.

USS SKIPJACK (SS18)


Page 106 of 200 Pages



AB-CR-MIG-6513-5. Buckle in floor at frame 90 of starboard safety tank. Looking outboard and down.

Page 107 of 200 Pages


USS SKIPJACK (SS184)




AB-CR-MIG-6526-7. Dents in port outer shell in way of fuel ballast tank No. 6.

USS SKIPJACK (SS184)

Page 108 of 200 Pages



AB-CR-MIG-6226-5. Dents in port outer shell in way of frames 44-58.



AB-CR-MIG-6528-12. Dent in tank top in way of main ballast tank 2 ${\tt C}$.

USS SKIPJACK (SS184)

Page 110 of 200 Pages



AB-CR-MIG-6529-1. Dent in tank top in way of main ballast tank $2\ \mathrm{D}$.



AB-CR-MIG-6520-3. "A" stiffener on after bulkhead of main ballast tank 2 B.


USS SKIPJACK (SS184)

Page 112 of 200 Pages



A B-CR-MIG-6525-4. Port shell in way of flood valves for main ballast tank No. 3.

USS SKIPJACK (SS184)



AB-CR-MIG-6525-3. Starboard shell in way of flood valves for main ballast tank No. 3.

USS SKIPJACK (SS184)

Page 114 of 200 Pages



AB-CR-MIG-6520-10. Deep frame No. 31 at bottom of main ballast tank No. 1 starboard.

Page 115 of 200 Pages

USS SKIPJACK (SS184)



AB -CR-MIG-6520-4. Upper bell crank assembly for flood valve in main bailast tank 2 B. Note bent shaft.

Page 116 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6520-7. Lower bell crank for flood valve in main ballast tank 2 B. Note interference with air flask.

USS SKIPJACK (SS184)

Page 117 of 200 Pages



AB-CR-MIG-6522-5. Ball socket joint on flood valve cover in main ball-ast tank 2 G.

USS SKIPJACK (SS184)

Page 118 of 200 Pages



AB-CR-MIG-6522-4. Damage to flood valve cover and links in main ballast tank 2 G.

SECRET '

Page 119 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6522-2. Damage to flood valve cover and links in main bullast tank 2 B.

USS SKIPJACK (SS184)

Page 120 of 200 Pages



AB-CR-MIG-6518-7. Flood valve cover for negative tank.

Page 121 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6527-2. Flood valve cover for negative tank.

1012

Page 122 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6519-3. Emergency vent valve clapper for main ballast tank 2 B. Note gasket.

USS SKIPJACK (SS184)

Page 123 of 200 Pages



AB-CR-MIG-6522-1. Emergency vent valve linkage for main ballast tank 2 E.

USS SKIPJACK (SS184)

Page 124 of 200 Pages



AB-CR-SM-6500-12. Split vent riser for fuel ballast tank No. 4.

Page 125 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6518-8. Main engine air induction valve, starboard side.

Page 126 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6514-11. Main engine air induction valve disc.

Page 127 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6519-11. Typical rubber gasket in inboard ventilation line.

Page 128 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6528-5. Bulkhead ventilation flapper valve in bulkhead 108, looking aft. Note gasket.

Page 129 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6512-5. Bulkhead ventilation flapper valve in bulkhead 130, looking aft. Note gasket.

Page 130 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6513-9. Machinery holding down bolts.

Page 131 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6522-9. #4 Main engine outboard exhaust valve, showing crack in casting.

USS SKIPJACK (SS184)

Page 132 of 200 Pages



AB-CR-MIG-6522-10. #4 Main engine outboard exhaust valve on side opposite to crack in casting.

USS SKIPJACK (SS184)



AB-CR-SM-6501-3. #2 Main engine muffler entering exhaust pipe.

Page 134 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6522-6. #2 Main engine muffler entering exhaust pipe showing pipe collapsed and pulled away from flange.

Page 135 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6513-6. #4 Main engine muffler showing dished in after end and distortion from pressure.

Page 136 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-SM-6501-1. Auxiliary engine muffler looking to port showing failure along butt weld.

USS SKIPJACK (SS184)

Page 137 of 200 Pages



AB-CR-MIG-6522-7. Auxiliary engine muffler showing rupture at center weld.

Page 138 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MuG-6517-7. #2 Main engine fresh water line to header. Leaks in silver soldering at reducing tee.

Page 139 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6517-6. #2 Main engine fresh water to header pipe, outboard of check valve.

USS SKIPJACK (SS184)


Page 140 of 200 Pages



AB-CR-MIG-6518-9. #1 Main engine gauge board, representative of all.

Page 141 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6518-9. #1 Main engine meter and control board, representative of all.

USS SKIPJACK (SS184)

Page 142 of 200 Pages



AB-CR-MIG-6516-11. Lubricating oil discharge from #4 Main engine lub oil cooler.

USS SKIFJACK (SS184)

Page 143 of 200 Pages



AB-CR-MIG-6507. Bow plane rigging gear worm gear case in forward torpedo room overhead showing crack in case.

USS SKIPJACK (SS184)

Page 144 of 200 Pages



AB-CR-MIG-0522-11. #1 H.P. air compressor showing crack in upper motor support.

Page 145 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6522-12. #2 H.P. air compressor snowing crack in upper motor support.

USS SKIPJACK (SS184)

Page 146 of 200 Pages



AB-CR-MIG-6520-2. High pressure air flask in main ballast tank 2 B, air bank #2, pipe adaptor broken off flask head.

USS SKIPJACK (SS184)


Page 147 of 200 Pages



AB-CR-MIG-6519-7. Accumulator air flask in pump room showing pipe adaptor broken off flask head.

USS SKIPJACK (SS184)

Page 148 of 200 Pages



AB-CR-MIG-6517-3. Section of fuel oil filling and transfer line at after bulkhead in crew's galley.

Page 149 of 200 Pages

USS SKIPJACK (SS184)




AB-CR-MIG-6517-2. Circulating water pipe for #4 main motor, port side of motor to reduction gear lub oil cooler.

USS SKIPJACK (SS184)



AB-CR-MIG-6516-9. Salt water circulating water discharge from #4 main motor cooler.



AB-CR-MIG-6517-4. #3 Main motor circulating water pipe from starboard side of motor cooler to reduction gear lubricating oil cooler.

USS SKIPJACK (SS184)

Page 152 of 200 Pages



AB-CR-MIG-6512-6. #2 Main motor sea suction valve.

Page 153 of 200 Pages


USS SKATE (SS184)



AB-CR-MIG-6514-12. #2 Main motor sea suction valve gasket for hull flange.

Page 154 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6511-1. Circulating water pipe for refrigerating plant.

Page 155 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6517-5. Sea water circulating water for air conditioning and refrigeration from strainer to pump.

Page 156 of 200 Pages

USS SKIPJACK (SS184)




AB-CR-MIG-6517-1. Broken line to oxygen bottle reducer, in after torpedo room at frame 171.

USS SKIPJACK (SS184)



AB-CR-MIG-6508-9. Starboard sound head shaft broken and slipped down.

USS SKIPJACK (SS184)



AB-CR-MIG-6508-6. Pitometer log master.

Page 159 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6513-7. Control cubicle starboard side front top foundation bolt.

USS SKIPJACK (SS184)

Page 160 of 200 Pages



AB-CR-MIG-6513-8. Control cubicle port side front top foundation action bolt.

USS SKIPJACK (SS184)


Page 161 of 200 Pages



AB-CR-MIG-6514-6. Propulsion control cubicle port & starboard motor starter contactors.

. USS SKIPJACK (SS184)


Page 162 of 200 Pages



AB-CR-MIG-6514-9. Propulsion control cubicle battery contactors.

Page 163 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6514-5. Propulsion control cubicle.


Page 164 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6514-7. Propulsion control cubicle Shunt and bussing for #2 propulsion generator.

USS SKIPJACK (SS184)



AB-CR-MIG-6514-3. Auxiliary power switchboard.

USS SKIPJACK (SS184)

Page 166 of 200 Pages



AB-CR-MIG-6514-4. Forward auxiliary power switchboard.

Page 167 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6511-6. Auxiliary power shore connection boxes.

Page 168 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6511-7. Auxiliary power shore connection boxes.

Page 169 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6514-2. General view of forward battery looking aft.

Page 170 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6513-1. "Minus" Disconnect switch-forward battery.

Page 171 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIK-6516-14. Sketch of forward battery vent duct arrangement and damage.

SECRET

Page 172 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6513-2. "Plus" Disconnect switch-forwart battery.

Page 173 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIK-6518-4. After battery cell #34 oil stains.

Page 174 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIK-6519-4. After battery - cracks in #8 cell case.

Page 175 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIK-6519-5. After battery - cracks in #34 cell case.

Page 176 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6514-1. General view of after battery looking forward.

USS SKIPJACK (SS184)

Page 177 of 200 Pages



AB-CR-MIG-6512-10. Intercoll connector after battery.

Page 178 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6512-8. After battery "plus" disconnect switch.

Page 179 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6512-9. After battery "minus" disconnect switch.

Page 180 of 200 Pages


USS SKIPJACK (SS184)




AB-CR-MIG-6512-11. Ventilation port side - after battery.

Page 181 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIK-6516-13. Sketch of after Battery vent duct arrangement and damage.



AB-CR-MIG-6506-10. Bow plane rigging and capstan motor.

SECRIT

Page 183 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6512-4. Bow plane rigging motor brush rigging.

USS SKIPJACK (SS184)

Page 184 of 200 Pages



AB-CR-MIG-6512-12. #1 Lubricating and fuel oil transfer pump motor.

Page 185 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6514-8. #2 Lubricating oil purifier pump motor.

Page 186 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-SM-6501-4 Forward anchor light from aft.

Page 187 cf 200 Pages

USS SKIPJACK (SS184)



AB-CR-SM-6501-5. Forward anchor light from deck level.

SECRET '

USS SKIPJACK (SS184)
Page 188 of 200 Pages



AB-CR-SM-6502-2. After anchor light.

. Page 189 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-SM-6502-1. Pressure proof blinker key.

USS SKIPJACK (SS184)


Page 190 of 200 Pages



AB-CR-MIG-6511-2. Mark 7 Mod. 0 #7003 gyro compass.

Page 191 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6511-3. Mark 7 Mcd. 0 #7003 gyro compass.




AB-CR-MIG-6524-9. Conning tower gyro repeater.



AB-CR-SM-6501-12. Bridge gyro repeater.

Page 194 of 200 Pages


USS SKIPJACK (SS184)



AB-CR-MIG-6511-12. D.R.A.indicator.

Page 195 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6511-4. Mark 9 auxiliary gyro compass Ser. 9262.

Page 196 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6511-11. 1 M.C. Power amplifier #1.

Page 197 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-SM-6501-8. Forward bridge pressure proof speaker and selector panel.

Page 198 of 200 Pages

USS SKIPJACK (SS184)




AB-CR-SM-6501-7. After bridge pressure proof speaker..

Page 199 of 200 Pages

USS SKIPJACK (SS184)



AB-CR-MIG-6511-10. Control room bow plane indicator.



USS SKIPJACK (SS184)

Page 200 of 200 Pages

679T



Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 4	XRD-203-Section 12
AD-366589	XRD-200-Section 9
AD-366590 L	XRD-204-Section 13
AD-366591 ►	XRD-183
✓ AD-366586 ★	XRD-201-Section 10
∠AD-367487. 以	XRD-131-Volume 2-
✓AD-367516 ¥	XRD- ₹ 143 ►
✓AD-367493 ✓	XRD-142 ►
AD-801410L	XRD-138
AD-376831L 🗸	XRD-83
AD-366759	XRD-80
✓AD-376830L ❖	XRD-79 ✓
✓AD-376828L 🌂	XRD-76 ∕
∠ AD-367464. ×	XRD-106 ✓
AD-801404L	XRD-105-Volume 1
✓AD-367459 🕱	XRD-100 ✓

TRC

Subject: Declassification of Reports

✓ AD-367517 🔾 XRD-141 ✔ AD-366762**▶** XRD-84 AD-366760 XRD-81 AD-366761 XRD-82 AD-367501 XRD-158-Volume 1 AD-367507L ✔ XRD-152-Volume 4 ✓ AD-367495 🖟 XRD-184 ✓ ✓AD-367485 🕏 XRD-129℃ ✓AD-367484 ¥ XRD-128 ✓ ✓AD-367483 🔏 XRD-127℃ ✓AD-367482**¥** XRD-126► AD-367488 XRD-132 AD-367480 XRD-124~ AD-801409L XRD-135 ✓AD-367490**火** XRD-136 ► ✓ AD-367492 ⊀ XRD-137► AD-801411L 🗸 XRD-139 ✓AD-367518 🔏 XRD-140 ✓

AD-367515 ✓ XRD-144

AD-367514 ✓ XRD-145

AD-367468 X XRD-110-Volume 2 V

AD-367513**√** XRD-146

AD-367497**X** XRD-162✓

TRC

Subject: Declassification of Reports

AD-801406L ✓ XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

ARDITH JARRETT
Chief, Technical Resource Center